



The New Era for Printing

Technical Service Bulletin	
File number : 2022004	Date: 1/4/2022 .
Publishing department : Customer Service Department	Page : 1 / 4

How to solve auto restart when sending printout

Release Object: Service Center

Maintenance Types :

Cartridge	☐	Installation	☐
Wireless Network	☐	Wired Network	☐
Paper	☐	App	☐
Print	☒	Scan	☐
Fax	☐	Set	☐
Firmware	☐	Others(hardware,etc)	☐

Applicable Model: Applicable to all series

UPDATING		
VERSION	MODIFIED CONTENTS	DATE


Written by : Leon	Verified by : Benson	Approved by : Herry
Date : 1/4/2022	Date : 1/4/2022	Date : 1/4/2022

Technical Service Bulletin	
File number : 2022004	Date: 1/4/2022 .
Publishing department : Customer Service Department	Page : 2 / 4

I. Problem Description

Phenomenon:

When sending a printout,the device restarts.



PANTUM

The New Era for Printing

Technical Service Bulletin	
File number : 2022004	Date: 1/4/2022 .
Publishing department : Customer Service Department	Page : 3 / 4




Technical Service Bulletin	
File number : 2022004	Date: 1/4/2022 .
Publishing department : Customer Service Department	Page : 4 / 4

II. Causes

There is defective connection in the data board.

III. Solution

Replace data board.



IV. Remark